DHT200 Humidity & Temperature Calibration Procedures

A. Humidity Calibration Procedures

- 1. Always start with a known good battery.
- 2. Dip the sensor probe of the ThermoHygrometer in the 75% REFERENCE CAPSULE, being sure the cotton does not contact the sensing tip. Wait 15 minutes and then use screwdriver to adjust set screw. Tune up to 75% on the Calibration Adjustment set screw (VR2) until display shows 75.0.
- 3. Repeat the procedure above two times for accuracy.

B. Temperature Calibration Procedure

- 1. Always start with a known good battery.
- 2. Place unit into a chamber that has a known temperature of 32°F or 0°C. Wait 15 mintures and then use screwdriver to adjust set screw (VR3) display until it reads 32.0 Fahrenheit or 0.0 Celcius.
- 3. Set chamber at 77°F or 25°C, and place unit inside. Wait until display is stable, then adjust set screw (VR4) with screwdriver until it displays 77.0 Fahrenheit or 25.0 Celcius.
- 4. Repeat steps 1 and 2 as needed.

