

>



Model Number: 2200638B
Tuthill 2200638B Repair Kit for Model 2004

Manufacturer: Tuthill

KIT CONSISTS OF BEARING, ROLL CYLINDER PART # 30410-203,

BEARING, BALL, 1 ROW PART # 30275-6203,

2 BEARING, BALL, 2 ROW PART # 30238-5203,

2 RETAINER PART # 2200538A,

1 SEAL, LIPW VITON PART# 2200548A,

4 SEAL, LIP W VITON PART# 2200558B,

2 SCREW, CAP, SOCKET HEAD PART# 90790-075,

6 SHIM, TIMING PART# 2200308B-003,

2 SHIM, TIMING PART# 2200308B-005,

2 SHIM, TIMING PART# 2200308B-010

AND 2 KEY, GEAR TIMING PART# 2200318B

Prices quoted are Ex Works, Springfield, MO USA. Minimum order \$50.
Tuthill Blower Brochure

Important Option

Oil level must be topped off on new blowers

>

Oil level must be changed after 50 hour break in period.
Oil level must be changed every 200 hours after break in period.
Gardner Denver 28G46 Brand Blower Oil Aeon PD-XD Full Synthetic Formula
Extra Heavy Duty for High Heat Applications 28G47-QT
Add to your shopping cart now!

Availability: This product was added to our catalog on Friday 28 June, 2019