

## SB, Motor Change, PRIME DM and PC, 2020-09

### SYMPTOM/DESCRIPTION

The motor cables in newly introduced K7000 and DM700 are a little thicker. To compensate for thicker cables a COVER KIT (figure 1) is included with each motor.

### AFFECTED UNITS

K6500 – All variants  
 K7000 – All variants  
 DM650  
 DM700




Figure 1: Cover kit in red circle

### PARTS INFORMATION

Part	Old article number	New article number
MOTOR ASSEMBLY PC	588729304	NLA
MOTOR ASSEMBLY DM	576214504	NLA
MOTOR KIT PC	New part	599637201
MOTOR KIT DM	New part	599637202

### WARRANTY INFORMATION

The normal warranty policy applies.

### Revision History

Rev.	Date	Order id.	Description
A	2020-09	SB-5957	Created