

>



Model Number: 6062.A9

Udor USA Kappa-25/33/43/53 Regulator Repair Kit - 6062.A9

Manufacturer: Udor USA

Udor USA Kappa-25/33/43/53 Regulator Repair Kit - 6062.A9

Description

6062.A9 is the standard repair kit for the Udor 6010.93 and 6010.95 Udor control unit. It includes the most common repair parts to ensure precise pressure control
Details

The 6062.A9 rebuild kit replaces the main internals on the Udor 6010.93 and 6010.95 regulators. These regulators are typically found on the Kappa-25/33/43/53 diaphragm pumps.

The rebuild kit includes one diaphragm (0903.26), a replacement poppet (1204.31), one replacement seat (1501.50), stainless steel bolt (1810.03) and replacement o-rings (1101.04, 1101.06, 1101.12, 1101.23)

The control unit rebuild should be incorporated into your preventative maintenance schedule.

Availability: This product was added to our catalog on Thursday 11 September, 2025