

>



Model Number: 5600638D

Tuthill 5600638D Repair Kit 3 Lobe 5000-22

Manufacturer: Tuthill

Tuthill Blower Brochure

Important Option

Oil level must be topped off on new blowers

Oil level must be changed after 50 hour break in period.

Oil level must be changed every 200 hours after break in period.

Gardner Denver 28G46 Brand Blower Oil Aeon PD-XD Full Synthetic Formula

Extra Heavy Duty for High Heat Applications 28G47-QT

Add to your shopping cart now!

*Availability: This product was added to our catalog on Thursday 09 April, 2026*