

>

Model Number: 4200098B  
Tuthill blower Repair kit 4200098B  
Manufacturer: Tuthill

Tuthill Blower Brochure

Important Option

Oil level must be topped off on new blowers  
Oil level must be changed after 50 hour break in period.  
Oil level must be changed every 200 hours after break in period.  
Gardner Denver 28G46 Brand Blower Oil Aeon PD-XD Full Synthetic Formula  
Extra Heavy Duty for High Heat Applications 28G47-QT  
Add to your shopping cart now!

---

*Availability: This product was added to our catalog on Saturday 19 January, 2013*