Equipment: Hard Surface Cleaning Supplies > Pressure Washer Accessories > Pump Kits > Karcher 2.884-512.0 VALVE (3X) REPLACES 45803290

Karcher 2.884-512.0 VALVE (3X) REPLACES 45803290



Model Number: 2.884-512.0

Karcher 2.884-512.0 VALVE (3X) REPLACES 45803290

Manufacturer: Karcher Pressure Washing

Kärcher 2.884-512.0 OEM Pump Valve Kit – Set of 3 Complete Valves
Genuine Kärcher replacement valve kit for select commercial hot- and cold-water pressure-washer pumps. This factory kit contains three complete pump valves and replaces several discontinued Kärcher valve part numbers, including 4.580-329.0.
Important: This listing is for one package containing 3 complete valves. It is not a single-valve listing.

Product details

Manufacturer
Kärcher

OEM order number
2.884-512.0

Unformatted part number
28845120

Package contents
3 complete pump valves

Part type
Pressure-washer pump valve kit

GTIN / EAN
4039784085688

Condition
New OEM replacement part

Steambrite Supply

Karcher 2.884-512.0 VALVE (3X) REPLACES 45803290

Supersedes these Kärcher numbers
Kärcher 2.884-512.0 is the current replacement kit for:

- 2.884-918.0
- 4.580-186.0
- 4.580-295.0
- 4.580-329.0

Reported pressure-washer applications
Published parts references show this valve set in select versions of the following Kärcher machines:

- 1500 Super
- G 4000 OH
- G 4000 RH
- G 4000 SH
- HD 3500 series
- HD 3501
- HD 3600 DH
- HD 575
- HDS 6/10-4 C
- HDS 10/20-4 M
- HDS 12/18-4 S
- HDS 557
- HDS 601 C / C Eco
- HDS 645-4 M
- HDS 6555
- HDS 1195 / 1195 S Eco
- K 1200 G / G Plus
- K 12000 GX
- K 14000 G

Confirm fit before ordering: Kärcher sometimes used different pumps or components within the same machine model. Match 2.884-512.0 or one of the superseded numbers to the parts diagram for your machine and serial number. A model-name match by itself does not guarantee fit.
Why replace pump valves?
Worn, contaminated, or sticking inlet and discharge valves can contribute to pressure-pump symptoms such as:

- Low or inconsistent operating pressure
- Pulsation or pressure fluctuation
- Reduced water flow
- Difficulty priming after the water supply and inlet filter have been checked

Steambrite Supply

Equipment: Hard Surface Cleaning Supplies > Pressure Washer Accessories > Pump Kits > Karcher 2.884-512.0 VALVE (3X) REPLACES 45803290

Karcher 2.884-512.0 VALVE (3X) REPLACES 45803290

These symptoms can also be caused by restricted water supply, clogged filters, air leaks, worn seals, nozzle problems, or an unloader malfunction. Diagnose the pump before ordering repair parts.
Installation notes

- Turn off the machine, disconnect electrical power or disable the engine, shut off the water supply, and fully relieve system pressure before service.
- Keep the valve bores and sealing surfaces clean during installation.
- Inspect related O-rings, seals, springs, valve seats, and pump oil as applicable.
- Install valves in the correct direction and torque components to the service-manual specification.
- Professional installation is recommended when pump service procedures are unfamiliar.

Genuine OEM Kärcher part
This is an original Kärcher replacement valve kit, not an aftermarket copy. Ordering by the complete OEM number helps identify the correct factory-specified replacement.

Brand and model names are used only to identify compatibility. Product appearance and packaging may change without notice. Always verify the required part number against the machine serial number and current manufacturer parts diagram before purchase.

Karcher 2.884-512.0 VALVE (3X) REPLACES 45803290

OEM / Old Part Number(s)

28845120
45802950
28845120
060-852
28845120
4039784085688

Availability: This product was added to our catalog on Wednesday 23 September, 2026