>

Model Number: B141B

Mytee 8400P Upholstery Wand Valve Repair Kit B141B

Manufacturer: Mytee Products Inc

Mytee 8400P Valve Repair Kit B141B

To repair valve leaks, 2-3 washers will be needed.
The third washer may be necessary depending on the spring tension of your tool.

Load tool and repair kit with Lithium grease to extend life

Do not allow the tool to freeze
Valve bodies that have been frozen, this repair kit will not fix any issues.

The part is not guaranteed to fix any issues and is non refundable/ returnable

Install instructions

Repairs

Mytee 8400P Air Lite Upholstery Tool Open Spray Auto Detail Wand with Freight Included GTIN 659937906598

Availability: This product was added to our catalog on Tuesday 23 April, 2024

Steambrite Supply