Equipment: Restoration > Dehumidifier > Rotomold Wheeled Dehumidifiers > DriStorm 202206214, Replacement Humidistat Sensor Cable for RH/1 to Coils Repair on AOne-70L and AOne-90L DriStorm Dehumidifiers

DriStorm 202206214, Replacement Humidistat Sensor Cable for RH/1 to Coils Repair on AOne-70L and AOne-90L DriStorm Dehumidifiers



Model Number: 202206214

DriStorm 202206214, Replacement Humidistat Sensor Cable for RH/1 to Coils Repair on AOne-70L and AOne-90L DriStorm Dehumidifiers

Manufacturer: Clean Storm

DriStorm 202206214, Replacement Humidistat Sensor Cable for RH/1 to Coils Repair on AOne-70L and AOne-90L DriStorm Dehumidifiers
Description
Replacement Humidistat Sensor Cable for RH/1 to Coils Repair on AOne-70L and AOne-90L DriStorm Dehumidifiers

Availability: This product was added to our catalog on Sunday 12 July, 2026

Steambrite Supply