


Parts & Accessories > Heaters > Heater Repair Parts > HydraMaster 000-038-098 HEAT EXCHANGER, 8R 6X8 SS 2 FIN

HydraMaster 000-038-098 HEAT EXCHANGER, 8R 6X8 SS 2 FIN



Model Number: 000-038-098

HydraMaster 000-038-098 HEAT EXCHANGER, 8R 6X8 SS 2 FIN

Manufacturer: HydraMaster

HydraMaster 000-038-098 Stainless Steel Heat Exchanger

HydraMaster Part Number: 000-038-098

Product: Truckmount Heat Exchanger

Construction: Stainless Steel (SS)

Configuration: 8 Row, 6" x 8", 2 Fin

Application: some HydraMaster Truckmounts

Parts Diagram Reference: Item #7

Product Description

The HydraMaster 000-038-098 is a stainless steel heat exchanger designed for use in the heating system of HydraMaster truckmounted carpet cleaning machines.

This heat exchanger is designed to transfer recovered heat into the truckmount cleaning solution, helping the machine produce the heated water required for professional carpet and upholstery cleaning applications.

The stainless steel construction provides durability for the demanding operating environment of commercial truckmounted cleaning equipment.

Product Specifications

Manufacturer
HydraMaster

Part Number
000-038-098

Component
Heat Exchanger

Material
Stainless Steel

Configuration
8 Row

Nominal Size
6" x 8"

Parts & Accessories > Heaters > Heater Repair Parts > HydraMaster 000-038-098 HEAT EXCHANGER, 8R 6X8 SS 2 FIN

HydraMaster 000-038-098 HEAT EXCHANGER, 8R 6X8 SS 2 FIN

Fin Specification
2 Fin

Equipment Application
HydraMaster CDS 4.8 Truckmount

Parts Diagram Position
#7

Heat Exchanger Function

HydraMaster truckmount cleaning systems utilize heat recovery technology to capture thermal energy produced during machine operation.

Heat exchangers transfer this recovered energy to the cleaning solution, reducing the need for a separate fuel-fired water heater.

The 000-038-098 heat exchanger is a replacement component for the heating system.

Common Reasons for Heat Exchanger Replacement

- Internal leakage or damaged heat exchanger tubing
- Reduced heating performance caused by internal restrictions
- Corrosion or deterioration of the existing component
- Physical damage to the heat exchanger assembly
- Replacement during truckmount heating system repairs

Manufacturer Information

Manufacturer: HydraMaster

Manufacturer Website: HydraMaster Official Website

Sold individually.

``` HydraMaster 000-038-098 HEAT EXCHANGER, 8R 6X8 SS 2 FIN for CDS 4.8 Truckmount  
#7 in image

Availability: This product was added to our catalog on Tuesday 20 October, 2026