
HydraMaster 000-078-802 â€" KIT, CDS RETRO 2003+ GM CLUTCH HOUSING



Model Number: 000-078-802

HydraMaster 000-078-802 â€" KIT, CDS RETRO 2003+ GM CLUTCH HOUSING

Manufacturer: HydraMaster

HydraMaster 000-078-802 CDS Retrofit Kit – 2003+ GM Clutch Housing
Genuine HydraMaster OEM Part Number 000-078-802 – CDS Retrofit Kit for 2003 and newer General Motors (GM) clutch housing applications.
The HydraMaster 000-078-802 CDS Retrofit Kit is a factory replacement and retrofit parts kit designed for applicable HydraMaster CDS (Clutch Drive System) truckmount carpet cleaning equipment installed in Chevrolet and GMC vehicles.
This kit is identified in HydraMaster factory parts documentation as KIT, CDS RETRO 2003+ GM CLUTCH HOUSING. It is intended for applicable CDS clutch housing retrofit and service applications.
Product Specifications

- Manufacturer: HydraMaster
- OEM Part Number: 000-078-802
- Factory Description: KIT, CDS RETRO 2003+ GM CLUTCH HOUSING
- Product Type: CDS Clutch Housing Retrofit Kit
- Equipment Application: HydraMaster CDS Direct-Drive Truckmount Systems
- Vehicle Manufacturer: General Motors (Chevrolet / GMC)
- Vehicle Application: Applicable 2003 and newer GM installations
- Condition: New OEM Replacement Part

HydraMaster CDS Direct-Drive Truckmount Applications
HydraMaster CDS systems are vehicle-powered truckmount carpet cleaning systems that utilize a clutch-driven power transmission arrangement. The front-end drive assembly transfers power from the vehicle engine to the CDS equipment.
The clutch housing and associated mounting components are important parts of this drive system. HydraMaster part number 000-078-802 is identified as a retrofit kit for applicable 2003+ GM clutch housing configurations.
Related HydraMaster CDS systems include the CDS 4.6 and CDS 4.8 product families. Specific kit applications and vehicle compatibility should be established using HydraMaster factory documentation.
Chevrolet and GMC Vehicle Applications
This retrofit kit is associated with HydraMaster CDS installations utilizing applicable General Motors clutch housing configurations introduced for the 2003 model year and later.
Applications may involve Chevrolet Express and GMC Savana commercial vans equipped with HydraMaster CDS direct-drive carpet cleaning systems.
Vehicle model year alone does not establish compatibility. Engine configuration, existing CDS equipment, front-end drive assembly, and factory installation requirements must be considered.
Related HydraMaster CDS Parts and Assemblies
The following HydraMaster part numbers are associated with related CDS front-end

HydraMaster 000-078-802 â€" KIT, CDS RETRO 2003+ GM CLUTCH HOUSING

drive components and assemblies. They are provided for technical reference and are not necessarily included with retrofit kit 000-078-802.

- 000-078-391: CDS Front-End Chevrolet Kit
- 000-015-879: Front Idler Casting Bracket, 2003+ Chevy
- 000-015-880: Rear Idler Casting Bracket, 2003+ Chevy
- 000-036-003: Clutch Assembly, 6-Inch Poly Groove
- 000-150-009: Electric Clutch Shaft

HydraMaster CDS Factory Service Documentation
HydraMaster factory service manuals contain exploded parts illustrations and technical information for CDS front-end drive assemblies.
HydraMaster CDS 4.6 / 4.8 Factory Owner's Manual (PDF)
HydraMaster CDS 4.8 Factory Service Manual (PDF)
Illustration Notice: Factory service manual illustrations may show complete CDS front-end assemblies or related components. These illustrations do not necessarily represent the individual parts supplied with kit 000-078-802.
Important Ordering Information
Order by manufacturer part number, not by image. Factory reserves the right to change product specifications, design, appearance, and included components without notice.
Manufacturer: HydraMaster
Part Number: 000-078-802
Factory Description: KIT, CDS RETRO 2003+ GM CLUTCH HOUSING

Availability: This product was added to our catalog on Monday 02 November, 2026

Steambrite Supply