Parts & Accessories > Swivels Pressure Rotary Union > Swivels Rotary Union Repair Kits > Mosmatic 36.905 Swivel Repair kit for Carbide swivels under 5000 psi

Mosmatic 36.905 Swivel Repair kit for Carbide swivels under 5000 psi



Model Number: 36.905

Mosmatic 36.905 Swivel Repair kit for Carbide swivels under 5000 psi

Manufacturer: Mosmatic

Mosmatic 36.905 Swivel Repair Kit for Carbide Swivels Under 5000 PSI
The Mosmatic 36.905 Swivel Repair Kit is designed for rebuilding select Mosmatic carbide seal swivels used in pressure washing, surface cleaning, and rotary union applications. This kit is intended for Mosmatic DY series carbide swivels rated above 2500 PSI and up to 5000 PSI.
Best Used For

- Repairing Mosmatic carbide seal swivels
- DY series swivel service and maintenance
- Surface cleaners and spinner tools using compatible Mosmatic swivels
- SX12 spinner wand swivel repair applications

Product Details

Brand
Mosmatic

Part Number
36.905

Product Type
Swivel / Rotary Union Repair Kit

Seal Type
Carbide Seal Kit

Pressure Range
For swivels rated over 2500 PSI up to 5000 PSI

Common Application
Mosmatic DY series swivels and compatible spinner wand assemblies

Steambrite Supply

Parts & Accessories > Swivels Pressure Rotary Union > Swivels Rotary Union Repair Kits > Mosmatic 36.905 Swivel Repair kit for Carbide swivels under 5000 psi

Mosmatic 36.905 Swivel Repair kit for Carbide swivels under 5000 psi

Cross Reference / Compare To

- Mosmatic 36.905
- Aramsco 2653-6829

Important Compatibility Note
Please confirm your swivel model before ordering. Repair kits are normally selected by the exact swivel series and part number, not only by pressure rating. Photos are for general reference only and may not show every small part included in the kit.
Why Repair Instead of Replace?
A worn swivel can leak, bind, lose pressure, or stop rotating smoothly. Rebuilding the swivel with the correct Mosmatic repair kit can restore performance and extend the service life of the existing rotary union, often at a lower cost than replacing the complete swivel assembly.
Ordering Notes

- Order by part number 36.905.
- Verify compatibility before installation.
- Specifications and kit contents are subject to factory change without notice.
- Installed repair parts are normally not returnable.

Search Terms
Mosmatic 36.905, Mosmatic 36905, Mosmatic swivel repair kit, carbide swivel seal kit, DY swivel repair kit, pressure washer swivel rebuild kit, rotary union repair kit, SX12 spinner wand swivel repair.

Instructions

Availability: This product was added to our catalog on Wednesday 10 October, 2012