# Karcher 8.707-370.0 Complete Seal Kit, Pumptec 356U, 360, 7531168



Model Number: 8.707-370.0

Karcher 8.707-370.0 Complete Seal Kit, Pumptec 356U, 360, 7531168

Manufacturer: Pumptec

Karcher 8.707-370.0 Complete Seal Kit for Pumptec 356U / 360 Pumps
Karcher 8.707-370.0 is a complete Pumptec seal kit used on select Pumptec 356U and 360 style pump heads found in Karcher, Landa, Legacy, Hotsy, and Shark equipment. This kit is commonly used when rebuilding a leaking or worn Pumptec pump head.
Part Numbers / Cross References

- Karcher: 8.707-370.0
- Alternate format: 87073700
- Pumptec association: 7531168 / 753168
- Legacy / Landa / Hotsy / Shark association: 2-3100533

Fits / Used On

- Pumptec 356U pump series
- Pumptec 360 pump series
- Selected Karcher, Landa, Legacy, Hotsy, and Shark machines using the compatible Pumptec pump head

When to Replace the Seal Kit

- Water leaking from the pump head
- Loss of pressure caused by worn seals
- Pump pulsation after valves and fittings have been checked
- Preventive rebuild during pump service

Important Ordering Notes

- Order by part number, not by photo. Images are for reference only.
- Verify your pump model and part number before ordering.
- This is a seal kit only. Valves, cam bearing assemblies, regulators, plungers, and complete pump heads are sold separately unless specifically stated.
- Specifications and factory part numbers can change without notice.

Related Repair Parts

- Karcher 8.707-369.0 Cam Bearing Assembly for Pumptec 356U / 360
- Pumptec valve kits for 356 / 360 pump heads
- Pumptec regulator and unloader repair parts
- Complete Pumptec pump and motor assemblies

Steambrite Supply

# Karcher 8.707-370.0 Complete Seal Kit, Pumptec 356U, 360, 7531168

SEO Search Terms
Karcher 8.707-370.0, 87073700, Pumptec 356U seal kit, Pumptec 360 seal kit, Pumptec complete seal kit, Landa 2-3100533, Hotsy Pumptec seal kit, Legacy Shark Pumptec pump repair kit, 7531168, 753168.
Karcher: Pumptec Complete Seal Kit 356u - 360 - 8.707-370.0 - Legacy Shark

OEM Associations

2-3100533

753168

87073700

Fixes Ferguson HT454 and HT89A Hydrostatic Test Pumps

*Availability: This product was added to our catalog on Friday 06 June, 2014*

Steambrite Supply