Karcher: Manifold Coil Outlet Discharge - 9.149-003.0 - Legacy Shark

Steambrite Supply

Parts & Accessories > Karcher Repair Parts > Karcher: Manifold Coil Outlet Discharge - 9.149-003.0 - Legacy Shark

Karcher: Manifold Coil Outlet Discharge - 9.149-003.0 - Legacy Shark



Model Number: 9.149-003.0

Karcher: Manifold Coil Outlet Discharge - 9.149-003.0 - Legacy Shark

Manufacturer: Karcher Pressure Washing

Karcher: Manifold Coil Outlet Discharge - 9.149-003.0 - Legacy Shark

OEM Associations

91490030

Availability: This product was added to our catalog on Friday 06 June, 2014

Steambrite Supply