Turboforce TH-15BOR Replacement Hard Boot Ring for the TH-15 Hybrid Wand



Model Number: TH-15BOR

Turboforce TH-15BOR Replacement Hard Boot Ring for the TH-15 Hybrid Wand

Manufacturer: Turbo Force

Turboforce TH-15BOR Replacement Hard Boot Ring for TH-15 Hybrid Wand
Part Number: TH-15BOR
OEM Association: TH15BOR
The Turboforce TH-15BOR is the replacement hard boot ring lip for the Turboforce TH-15 Hybrid Wand. This ring helps restore the bottom contact surface of the tool when the original hard boot ring is worn, damaged, or no longer sealing correctly against hard floor surfaces.
Fits

- Turboforce TH-15 Hybrid Wand
- 15 inch Turbo Hybrid hard surface cleaning wand

Why Replace This Ring?

- Helps restore proper floor contact
- Helps maintain vacuum recovery around the cleaning head
- Replaces a worn or damaged hard boot ring lip
- Lower-cost repair option compared to replacing the complete wand

Important Ordering Note
Please verify your wand model before ordering. This listing is for the TH-15BOR hard boot ring only. It is not the TH-15BR brush ring, not the complete wand, and not the 12 inch TH-260 ring used on the TH-40 tool.
What You Get

- One replacement hard boot ring for the Turboforce TH-15 Hybrid Wand

Common Search Terms
Turboforce TH15BOR, TH-15BOR, TH15 hard boot ring, TH-15 Teflon ring, Turboforce Hybrid Wand ring, 15 inch hard surface wand repair part.
Repairs your Turboforce TH-15 Hybrid wand hard boot ring lip

Availability: This product was added to our catalog on Wednesday 21 December, 2016

Steambrite Supply