Kohler PA-CH640-3230 Engine 20.5 hp Command Pro GTIN N/A



Model Number: PA-CH640-3230
Kohler PA-CH640-3230 Engine 20.5 hp Command Pro GTIN N/A

Manufacturer: Kohler



Replaces Old Kohler Spec # PS64503, 64503, CH640-3004, CH640-3205
Good Replacement for 62613
Engine Controls-Key Switch, Throttle and Choke Controls
Overhead Valve Design
Hydraulic Valve Lifters

Kohler PA-CH640-3230 Engine 20.5 hp Command Pro GTIN N/A

Cast-Iron Cylinder Liners
Electronic Ignition
Large Capacity Dual Element Air Cleaner
High Efficiency Grass Screen and Fan
Closed Breather System
Stellite Exhaust Valves
Full Pressure Lubrication
Large Capacity In-Line Fuel Filter
Easy Access Valve Cover Oil Fill-Yellow
Oil Level Dipstick-Yellow
Large Capacity Oil Filter, Dual Oil Drain
Oil Sentry (Switch Installed and Wired but Unconnected)
Variable Speed Governor
Fuel Shutdown Solenoid, Smart-Choke Carburetor
Mechanical Fuel Pump
High Performance Spark Plugs
12 Volt Solenoid Shift Starter
15 Amp Alternator, Regulated
Crankshaft-1.125" (1 1/8")(28.5 mm) Diameter x 4.0" (102 mm) PTO Length, 0.25" (6 mm) Keyway, Drilled and Tapped 1.5" (38 mm) Deep, 7/16-20 UNF
PTO Face-5.625" (143 mm) Diameter, (4 Holes) 3/8-16 x 0.67" (17 mm) Deep, 7.75" (197 mm) Diameter, (4 Holes) 7/16-14 x 0.83" (21 mm) Deep 7" (178 mm) Diameter Pilot

Options available for Kohler PA-CH640-3230 Engine 20.5 hp Command Pro GTIN N/A :

Shipping Surcharges

Home Delivery Needs Liftgate Curb Service Because No Forklift On Site (Required) No Appointment Provided, None Commercial Address Forklift / Loading Dock On Site No Appointment Provided, +Home Delivery Needs Liftgate Curb Service Because No Forklift On Site With Appointment Delivery Time, Commercial Address But Needs Liftgate Service Because No Forklift or Dock on Site No Appointment Provided.

Availability: This product was added to our catalog on Thursday 10 February, 2022