Parts & Accessories > Engines > Kohler Command PRO EFI Series (ECH/ECV) > Kohler PA-ECH980-3001 Comand Pro 35Hp Horizontal Engine Chrakshaft 1.437 X 4.46 No factory installed key switch GTIN N/A

Kohler PA-ECH980-3001 Comand Pro 35Hp Horizontal Engine Chrakshaft 1.437 X 4.46 No factory installed key switch GTIN N/A



Model Number: PA-ECH980-3001

Kohler PA-ECH980-3001 Comand Pro 35Hp Horizontal Engine Chrakshaft 1.437 X 4.46 No factory installed key switch GTIN N/A

Manufacturer: Kohler

Overview
Kohler 35.0 hp Engine PA-ECH980-3001 Command Pro Basic Heavy Duty Air Cleaner
Crank 62 014 113 Diameter 1.437" X 4.46"
No factory installed key switch or controls
Wire harness # 62 176 44

HP	
Shaft	
Cylinders	
Cooling	
Fuel Type	
	Horizontal V-Twin Air Gasoline

Freight shipping surcharges are not free so please add to shopping cart. If you check

Steambrite Supply

Kohler PA-ECH980-3001 Comand Pro 35Hp Horizontal Engine Chrakshaft 1.437 X 4.46 No factory installed key switch GTIN N/A

out with the wrong receiving environment, your order will be placed on hold.

Features

- High-performance spark plugs
- 25 amp charging, regulator
- Larger in-line fuel filter
- Overhead valve (OHV) design
- Heavy-duty air cleaner
- Integrated oil cooler
- Heavy-duty bearings
- Hardened crank shaft journals
- High-efficiency fan and screen
- Cast iron cylinder liners
- Full pressure lubrication
- Spin on, full-flow oil filter
- Two-barrel carburetor
- Electronic ignition system
- Solenoid shift starter
- Mechanical fuel pump
- Nylon Cam Gear
- Hydraulic valve lifters
- Modulated cooling fan
- Engineered material blower housing
- CARB & EPA emission-certified
- Top mounted quick change oil filter
- Extended maintenance intervals
- Yellow oil fill cap & dipstick handle
- Large dual oil drains for faster oil changes
- Easy access oil fill/dipstick

Specs

Engine Type:
4-cycle, gasoline, OHV, cast iron cylinder liners, aluminum block.

Steambrite Supply

Kohler PA-ECH980-3001 Comand Pro 35Hp Horizontal Engine Chrakshaft 1.437 X 4.46 No factory installed key switch GTIN N/A

Model

Command PRO CH940

J1940 Power hp(kW)
32.5 (24.2)

Displacement cu in (cc)
61 (999)

Bore in (mm)
3.5 (90)

Stroke in (mm)
3.1 (78.5)

Peak Torque lbs. ft (Nm)
53.5 (72.5)

Compression Ratio
8.8:1

Dry Weight lbs (kg)
132 (59)

Oil Capacity U.S. quarts (L)
2.1 (2)

Lubrication
Full pressure w/full-flow filter

Steambrite Supply

Kohler PA-ECH980-3001 Comand Pro 35Hp Horizontal Engine Chrakshaft 1.437 X 4.46 No factory installed key switch GTIN N/A

Dimensions L x W x H in
15.3 x 19.0 x 27.5

Backpressure Limit
40

J1995 Power hp (kW)
31.84 (23.74)

J1995 Rated Speed (RPM)
3600

Parts to consider with this purchase:

Kohler 62 164 11-S Exhaust Manifold Starter Side Discharge for CH940 Through CH1000 6216411-S

Kohler 62 164 10-S Exhaust Manifold Non-Starter Side Discharge for CH940 Through CH1000 6216410-S

Steambrite Supply

Kohler PA-ECH980-3001 Comand Pro 35Hp Horizontal Engine Chrakshaft 1.437 X 4.46 No factory installed key switch GTIN N/A

Kohler 62 068 10-S Muffler kit for CH940 through CH1000 Series 6206810-S

Kohler 62 376 02-S OH Engine Controls for CH940 through CH1000 engines Control panel

Options available for Kohler PA-ECH980-3001 Comand Pro 35Hp Horizontal Engine Chrakshaft 1.437 X 4.46 No factory installed key switch GTIN N/A :

Shipping Surcharges

Parts & Accessories > Engines > Kohler Command PRO EFI Series (ECH/ECV) > Kohler PA-ECH980-3001 Comand Pro 35Hp Horizontal Engine Chrakshaft 1.437 X 4.46 No factory installed key switch GTIN N/A

Kohler PA-ECH980-3001 Comand Pro 35Hp Horizontal Engine Chrakshaft 1.437 X 4.46 No factory installed key switch GTIN N/A

Commercial Address But Needs Liftgate Service Because No Forklift or Dock on Site No Appointment Provided, Residential Forklift Onsite Limited Access + Needs Appointment, Home Delivery Needs Liftgate Curb Service Because No Forklift On Site (Required) No Appointment Provided, None Commercial Address Forklift / Loading Dock On Site No Appointment Provided, Commercial Address But Need Liftgate and Appointment Service / Limited Access Fee Not Included, +Home Delivery Needs Liftgate Curb Service Because No Forklift On Site With Appointment Delivery Time.

Availability: This product was added to our catalog on Friday 25 August, 2023

Steambrite Supply