Kohler PA-ECV940-3015 Exmark 35 Hp Engine Crankshaft 1.125 X 432L HDAC 20Amp Charging Wire Harness GTIN N/A



Model Number: PA-ECV940-3015

Kohler PA-ECV940-3015 Exmark 35 Hp Engine Crankshaft 1.125 X 432L HDAC 20Amp Charging Wire Harness GTIN N/A

Manufacturer: Kohler

Kohler PA-ECV940-3015 Exmark 35 Hp Engine

Crankshaft 62 014 124 1.125" X 4.30"
Heavy Duty Air Cleaner
No Key switch or Choke Installed
20 Amp charging
Wire Harness 62 176 32 With E-gov
No muffler
Factory Installed fuel pump

Features :

- Top mounted quick change oil filter
- Extended maintenance intervals
- Large dual oil drains for faster oil changes
- High performance spark plugs
- Larger in-line fuel filter
- Heavy duty air cleaner
- Hardened crankshaft journals
- Hydraulic valve lifters
- Electronic ignition system

Specifications :

- 4-cycle gasoline
- Vertical shaft
- V-twin cylinders
- Air cooled
- Aluminum block
- 32.5 horse power
- 999cc
- 3.5 inch bore
- 3.1 inch stroke
- 53.6 ft lb peak torque
- 8.8:1 compression ratio
- 127 pounds dry weight
- 2.1 quart oil capacity
- 3600 RPM

Steambrite Supply

Parts & Accessories > Engines > Kohler PA-ECV940 Engines > Kohler PA-ECV940-3015 Exmark 35 Hp Engine Crankshaft 1.125 X 432L HDAC 20Amp Charging Wire Harness GTIN N/A

Kohler PA-ECV940-3015 Exmark 35 Hp Engine Crankshaft 1.125 X 432L HDAC 20Amp Charging Wire Harness GTIN N/A

https://sleequipment.com/kohler-ecv940-3012-command-pro-32-5hp-999cc-vertical-engine.html $3892.00 + shipping

-->

Options available for Kohler PA-ECV940-3015 Exmark 35 Hp Engine Crankshaft 1.125 X 432L HDAC 20Amp

Charging Wire Harness GTIN N/A :

Shipping Surcharges

Residential Forklift Onsite Limited Access + Needs Appointment, Home Delivery Needs Liftgate Curb Service Because No Forklift On Site (Required) No Appointment Provided, None Commercial Address Forklift / Loading Dock On Site No Appointment Provided, Commercial Address But Need Liftgate and Appointment Service / Limited Access Fee Not Included, +Home Delivery Needs Liftgate Curb Service Because No Forklift On Site With Appointment Delivery Time, Commercial Address But Needs Liftgate Service Because No Forklift or Dock on Site No Appointment Provided.

Availability: This product was added to our catalog on Tuesday 29 August, 2023

Steambrite Supply