






!! IMPORTANT !!
TERMINAL STRIP IS ON LEFT SIDE OF MACHINE ON BACK WALL.
FIELD WIRING MUST COMPLY WITH LOCAL AND NATIONAL ELECTRICAL CODES.
20AMP SERVICE IS REQUIRED FOR DEVILBISS UNITS


!! IMPORTANT !!
TERMINAL STRIP IS ON LEFT SIDE OF MACHINE ON BACK WALL.
FIELD WIRING MUST COMPLY WITH LOCAL AND NATIONAL ELECTRICAL CODES.
10AMP SERVICE IS REQUIRED FOR TWIN THOMAS & GAST UNITS



FACTORY WIRING
FIELD WIRING



SWITCH CONNECTIONS ARE THE BLUE WIRES CURRENTLY SHOWN GOING TO THE COIN ACCEPTOR. WHEN SWITCH IS USED COIN ACCEPTOR IS NOT USED.

<div><div></div><div></div></div> <p>SWITCH CONNECTIONS ARE THE BLUE WIRES CURRENTLY SHOWN GOING TO THE COIN ACCEPTOR. WHEN SWITCH IS USED COIN ACCEPTOR IS NOT USED.</p> <p>8726</p>					120 VAC		120 VAC		120 VAC (GR)	
					TITLE					
					8670 SERIES, SSAC, ALL COMPRESSORS					
UNSPECIFIED TOLERANCES		SCALE		<div><p>CEDAR RAPIDS, IOWA</p></div>		-		PART NO.		
FRACT. $\pm 1/32$		DRAWN BY				8670 SERIES SSAC				
2 PL $\pm .020$		CK				REV.				
3 PL $\pm .010$		DATE		7-27-10		-				
ANGLE $\pm 1.0^\circ$		REL. FOR PROD.		-						