

SB, New handle, WA20, RA10, RA10S, 2021-02

SYMPTOM/DESCRIPTION

A new handle with a new knob has been developed. The new knob is not backwards compatible. As neither the WA20 nor the RA10 has a serial number, one has to look at the units to see the difference. The old parts will no longer be available. The new knobs are attached to the handle with a circlip instead of threads.

AFFECTED UNITS

WA20
RA10
RA10S

CORRECTIVE ACTION

If the handle or knob needs to be replaced on an older product, new LOCKING HANDLE needs to be ordered. When the new LOCKING HANDLE is in place, new knob and circlip should be used.



Figure 1: New knob



Figure 2: New knob

PARTS INFORMATION

Part	Old article number	New article number
KNOB	506385401	Used Elsewhere
HANDLE	506227604	NLA
LOCKING HANDLE	506226903/506226905	597464001
LOCKING HANDLE	506226904/506226906	597464002
ARM BASE ASSY	544923403	544923401
KNOB	New part	596474301
HANDLE	New part	593207401
CIRCLIP	New part	735311000

WARRANTY INFORMATION

The normal warranty policy applies.

Revision History

Rev.	Date	Order id.	Description
<i>A</i>	<i>2021-02</i>	<i>SB-6440</i>	<i>Created</i>