



IMPORTANT ACTION RECOMMENDED HVE 3000 Flood Extractor All models

Date: September 3, 2015
To: HVE 3000 Flood Extractor Customers
RN#: 150903
RE: HVE 3000 Flood Extractor, all models

To protect your valuable equipment and prevent voiding the warranty, we recommend the following procedures:

- Install the HEPA filter (*part no. F503, case of 4*) when using the HVE 3000 on Category 3 restoration jobs or where quieter operation is preferred. The filter is located behind the filter shroud – see illustration below
- Remove and discard filter at the end of the all Category 3 restoration jobs.
- On all other jobs, we recommend operating the unit without the HEPA filter in place. Hearing protection is recommended when the filter is not in place.
- Use defoaming chemicals whenever foam is present in waste tank.
- Replace the HEPA filter if it gets wet during operation.
- If foam/water is pulled through the vacuum blowers, remove hose/wand and run blower unit for 5 minutes to dry out the system prior to storing.

Failure to follow these instructions can damage the vacuum system and will void the warranty.

NOTICE CONTINUES ON NEXT PAGE

In addition, we recommend replacing the vacuum blower brushes after 800 hours of operation.


Detailed instructions for these procedures are described in your owner's manual. Copies of the owner's manual are available for download at the [HVE 3000.DriEaz.com](http://HVE3000.DriEaz.com).

To order filters or brush replacement kits, contact your local Dri-Eaz or Sapphire distributor or call Legend Brands at 800-932-3030.

Replacement HEPA Filters (case of 4): F503 / 20-045

Vacuum Blower Brush Replacement Kit: S506

Defoamer Pellet (case of 12): F556 / 76-530



HEPA exhaust filter grill.

Thumbscrews allow easy filter replacement. To order replacements, ask for part no. F503 / 20-045, case of 4.