

>



Model Number: 8.617-754.0

Legend Brands 109100 Throttle Cable | Prochem 40-031 | Karcher 8.617-754.0 86177540 | Hydramaster 000-025-033

Manufacturer: Prochem

Legend Brands 109100 Throttle Cable | Sapphire Scientific 40-031 | Karcher 8.617-754.0 86177540 | Hydramaster 000-025-033 Push Button Throttle Cable Control

Part Number: 8.617-754.0 / 86177540 / 40-031 / 000-025-033 / Legend Brands 109100

Replacement push-button throttle cable control used on select Prochem, Sapphire Scientific, White Magic, Hydramaster, Blue Baron, Blazer, Peak, and other truckmount carpet cleaning machines. This cable is designed as a field-replacement throttle control and may need to be cut or adjusted to fit your exact truckmount application.

Key Features

- Push-button style throttle cable control
- Used on many truckmount carpet cleaning machines
- Heavy-duty replacement style cable
- Cut-to-fit for many applications
- Commonly used on Blazer, Peak, Blue Baron, Prochem, Sapphire Scientific, White Magic, and Hydramaster truckmounts

Known OEM / Cross Reference Numbers

Prochem / Karcher
8.617-754.0, 86177540, 40-031

Sapphire Scientific
40-031

Hydramaster
000-025-033

Other References
PP791096, 791096, 5520, 109100, J412

Important Fitment Note

This is a replacement throttle cable control and is not guaranteed to be a direct drop-in part for every machine. Compare your existing cable, mounting style,

>

knob/button type, and total length before ordering. Some installations require trimming, routing adjustment, or reuse of original mounting hardware. Has to be cut to fit for you application.

This new style, to the right, is also thicker, more heavy duty jack than the original, so hopefully will last longer.

Recommended Before Ordering

- Confirm your old part number matches one of the listed cross-reference numbers.
- Compare the product photo to your existing throttle control.
- Measure your original cable if exact fit is critical.
- Verify that your throttle linkage moves freely before replacing the cable.

Common Symptoms of a Bad Throttle Cable

- Engine will not hold high or low throttle position
- Throttle button/knob is stiff, loose, broken, or slipping
- Cable is kinked, frayed, rusted, or melted
- Truckmount engine speed will not adjust correctly

SEO Search Terms

Prochem 40-031 throttle cable, Prochem 86177540 throttle control, Karcher 8.617-754.0 cable, Hydramaster 000-025-033 throttle cable, Sapphire Scientific 40-031, Blazer truckmount throttle cable, Peak truckmount throttle control, Blue Baron throttle cable, White Magic throttle cable, carpet cleaning truckmount throttle cable. Prochem, Hydramaster Throttle Control Blazer, Blue Baron, or other Truckmounts

Compare to current or past OEM associations:

PP791096
Sapphire Scientific 40-031
86177540
8.617-754.0
Blue Baron 791096
Hydramaster 000-025-033
5520
Legend Brands 109100
White Magic J412

Replacement push-button throttle cable control for select Prochem, Sapphire Scientific, White Magic, Hydramaster, Blazer, Peak, Blue Baron, and other truckmount carpet cleaning machines. Cross references 8.617-754.0, 86177540, 40-031, and 000-025-033.

Availability: This product was added to our catalog on Monday 07 January, 2013