

>



Model Number: 8.751-237.0

Karcher 8.751-237.0 Plunger Kit, 18mm, 1 Each - 87512370 - Legacy Shark

Manufacturer: Karcher Pressure Washing

Karcher 8.751-237.0 Plunger Kit, 18mm, 1 Each - 87512370 - Legacy Shark

NOTE: If replacing all three ceramic plungers on your pump, Please order 3 kits. Sold individually!

Description

Cracked or broken ceramic piston sleeves can cause further pump damage if not repaired immediately. Some pump damage can be so extensive as to require replacement of the entire pump. Identification of broken or cracked ceramic plunger sleeves can be difficult, however one sign to look for is milky or caramel colored pump oil, which indicates water has entered the pump body and mixed with the pump oil.

This 8.751-237.0 Ceramic Piston Sleeve Repair Kit includes all components necessary to replace the ceramic plunger for one pump cylinder. Included in the kit is: one ceramic piston sleeve, one piston / plunger bolt, one o-ring and one copper spacer.

Additional Information

Ceramic plunger kit, 18mm (8.751-237.0) fits the following pump models:

Landa Pump Models

LM-4035

LM-4035-H

LM-4035-R.3

LM-4035-L.3

LM-6035-R.3

LM-6035-L.3

Legacy Pump Models

GM 4035.3

GM 6035.3

Hotsy Pump Models

HM 4035.3

Karcher Pump Models

KM4035.2

KM4035.3

KM6035.2

KM6035.3

Cross Reference Skus

87512370

8.751-237.0

>

Availability: This product was added to our catalog on Friday 06 June, 2014