

>



Model Number: T5

Aftermarket Turbo Force T5, Replacement Spray Bar Self Assembly, for Th-40 (Self Assembly of Hub, Spray Arm, Jet Holder)

Manufacturer: Clean Storm

Aftermarket Turbo Force T5 Replacement Spray Bar Self-Assembly Kit for TH-40  
Restore the cleaning performance of your Turbo Force TH-40 Turbo Hybrid tile and grout spinner tool with this economical aftermarket T5 replacement spray bar kit. This version is supplied as individual components and requires assembly by the user, making it an excellent low-cost alternative to purchasing a factory-assembled spray bar.

Features

- Compatible with Turbo Force TH-40 Turbo Hybrid spinner tools
- Economical aftermarket replacement
- Includes hub, spray arm, and jet holder components
- User assembly required
- Ideal for repairing damaged, bent, or worn spray bars
- Helps restore balanced rotation and cleaning performance
- Lower cost than factory preassembled versions

What's Included

- Spray bar hub
- Spray arm
- Jet holder assembly
- Self-assembly hardware as supplied by manufacturer

Not Included

- Spray jets
- Spinner head
- Swivel assembly
- TH-40 cleaning tool

Common Reasons for Replacement

- Spray bar bent after impact with hard objects
- Uneven spray pattern
- Reduced spinner speed
- Vibration during operation
- Corrosion from chemical exposure
- Routine maintenance on high-hour machines

Why Choose The Self-Assembly Version?

The self-assembly version offers substantial savings compared to purchasing a factory assembled T5 spray bar. Professional cleaners who are comfortable with basic tool repair can install the components themselves and return their TH-40 Turbo

>

Hybrid to service quickly.  
Compatible Equipment

Machine  
Compatible

Turbo Force TH-40 Turbo Hybrid  
Yes

Turbo Force TH-15  
No

Turbo Force Mini Turbo  
No

#### Maintenance Tip

Whenever replacing a spray bar, inspect the swivel, spray jets, filter screen, quick connects, and brush ring. A worn swivel or partially clogged jet can reduce spinner performance even after installing a new spray bar.

#### Frequently Asked Questions

Q: Is this a factory OEM Turbo Force part?

A: No. This is an aftermarket replacement designed to fit the TH-40.

Q: Does it arrive assembled?

A: No. This version requires assembly of the hub, spray arm, and jet holder.

Q: Are spray jets included?

A: Verify current package contents before ordering. Jets are commonly sold separately.

Q: Why is this version less expensive?

A: Assembly labor is not included, allowing significant cost savings over factory assembled versions.

#### Turbo Force T5 Replacement Spray Bar Assembly for Th-40

##### Description

Sold with hub, + 2 spray arms, + 2 angle jet holder.

Self assemble with teflon tape, Thread Lock or Enamel Clear coat (Finger Nail Polish).

Set to 24 degree angle.

Optional

>

Don't like to work with your hands, don't want to self assemble, purchase it pre-assembled

Turbo Force T-5 Replacement Spray Bar Complete for Th-40 OEM

NOTE: Diameter of Spray arm when fully assembled is 10 & 9/16ths, which may not fit older models built before 2018, please confirm bar diameter before ordering.

(If uncertain, then recommended to order the OEM version linked above)

TH-40 Spray Bar Options Comparison

Feature

Self-Assembly T5  
OEM Complete T5

Price

Lower  
Higher

User Assembly Required

Yes  
No

Installation Time

Longer  
Shorter

Best For

Budget-minded repair  
Fastest repair

Turbo Force T5, TH40 spray bar, Turbo Hybrid spray arm, TH40 repair parts, Turbo Force replacement spray bar, spinner tool repair, tile cleaning tool parts, hard surface spinner repair, T5 spray bar assembly, Turbo Force TH40 parts

>

*Availability: This product was added to our catalog on Thursday 23 February, 2017*

Steambrite Supply