

>



Model Number: T-5

Turbo Force T-5, Replacement Spray Bar Complete, for Th-40 OEM

Manufacturer: Turbo Force

Turbo Force T-5 Replacement Spray Bar Complete for TH-40
OEM Turbo Force T-5 complete replacement spray bar assembly for the Turbo Force TH-40 hard surface spinner tool. This is the preassembled version, designed to save installation time versus building the spray bar from loose components.

- Part Number: T-5
- Fits: Turbo Force TH-40
- Assembly: Complete replacement spray bar, no assembly required
- Factory Setting: Pre-set to a 24-degree spray angle
- Jets / Nozzles: Not included
- Use: Replaces worn, bent, damaged, or corroded spray bar assemblies

Why Replace the Spray Bar?

A damaged or worn spray bar can cause uneven spray pattern, streaking, poor cleaning performance, vibration, or improper spinner operation. Replacing the complete spray bar helps restore the correct spray angle and balanced water delivery.
Important Ordering Notes

- This listing is for the complete preassembled T-5 spray bar.
- No spray jets are included. Reuse your existing jets if serviceable or order replacement jets separately.
- Factory pre-set angle is 24 degrees.
- Images are for reference only. Always order by part number.

Preassembled vs. Self-Assembly Version

Option
Best For
Notes

T-5 Complete Spray Bar
Fastest repair with less setup time
Preassembled and factory set

Self-Assembly Version
Customers wanting lower cost
Requires assembly of hub, spray arm, and jet holder

Related Parts Often Replaced at the Same Time

>

- Turbo Force TH-40 / TH-15 swivel assemblies
- 1/8 inch spray jets / VeeJet nozzles
- Rotary arm and spray bar hardware
- Seal, fitting, and bulkhead components

Compatibility Reminder

This part is intended for the Turbo Force TH-40. Before ordering, compare your existing part number, spray bar style, and machine model. If your current spray pattern is uneven, also inspect the jets for clogging or wear.

Suggested Meta Title

Turbo Force T-5 Replacement Spray Bar Complete for TH-40 Spinner Tool

Suggested Meta Description

OEM Turbo Force T-5 complete replacement spray bar for TH-40 hard surface spinner tools. Preassembled, factory set to 24 degrees. No spray jets included.

Suggested Search Keywords

Turbo Force T-5, TH-40 spray bar, Turbo Force replacement spray bar, TH40 spinner spray arm, hard surface tool spray bar, Turbo Force parts, tile cleaning spinner parts
Why pay more for OEM?

Unlike aftermarket or self-assembly spray bar kits, this OEM Turbo Force T-5 assembly arrives factory assembled and correctly aligned for TH-40 Turbo Hybrid tools. Simply transfer your jets (or install new jets) and return your spinner to service with minimal downtime.

Turbo Force T-5 Replacement Spray Bar Complete for Th-40

Description

Turbo Force T-5 Replacement Spray Bar Complete (no assembly needed) for Th-40
Factory pre-Set to 24 degree angle.

No jets Included.

Min factory shipping charge for this item is \$25.00

Also see optional generic option

Turbo Force T5 Replacement Spray Bar Self Assembly for Th-40
Save \$55 to self assemble over preassembled.

Turbo Force T5, TH40 spray bar, Turbo Hybrid spray arm, TH40 repair parts, Turbo Force replacement spray bar, spinner tool repair, tile cleaning tool parts, hard surface spinner repair, T5 spray bar assembly, Turbo Force TH40 parts
TH-40 Spray Bar Options Comparison

>

Feature
Self-Assembly T5
OEM Complete T5

Price
Lower
Higher

User Assembly Required
Yes
No

Installation Time
Longer
Shorter

Best For
Budget-minded repair
Fastest repair

Availability: This product was added to our catalog on Monday 02 March, 2020