

>



Model Number: SBME519F

Clean Storm SBME519F, 1000 Watt Heating Rod Element, Heater repair 115V E519 10-1500-A Rotovac TE228100

Manufacturer: Clean Storm

Clean Storm 1000 Watt Heating Rod Element Heater repair 115 volts E519

Replacement heater rod for most brands of carpet cleaning machines including but not limited to

Mytee, Sandia, Clean Storm, US Products, Rotovac Enduro, Prospector

Rod is 1/2" thick and 7-1/8" long (without wire leads included in the measurement)

Wire leads are permanently attached.

1000 watts @ 120 volts / 8.33 amps.

Compare to current or past OEM associations:

Clean Storm SBME519F

Mytee E519

Sandia Plastic / Prospector 10-1500-A

Rotovac TE228100

REV A1151KW

MYE519

101500A

MP-101500A-EA

MF-10-1500-A

This requires that the solderless connections be replaced.

Please note it is NOT OK to use 12 volt rated automotive connectors made out of vinyl.

You must use nylon connectors instead rated for 120 volts.

Using the wrong connections can cause your machine to catch on fire!

Fully Nylon-Insulated Female EZ Disconnect 14-16 AWG each 4X299-1
BLUE Solderless Connector 1/4in Wide

<https://www.kleen-ritecorp.com/p-44810-mytee-e519-heating-rod-1000-watt-115-volt.aspx> \$45.06

-->

<https://www.mytee.com/products/e519-heating-rod/> \$62.91

https://www.discountcleaningproducts.com/Sandia-10-1500-A-Heater-Element-1000-Watt-p/10-1500-a.htm?gclid=CjwKCAjw_b6WBhAQEiwAp4HyILOJmVFwO50dDvhCp_nOzrbKpe-qUSvu7l1UY23FAsQA9tpfllEnJBoCs-gQAvD_BwE \$73.94

>

<https://www.cleaningstuff.net/sandia-101500a-1000-watt-heating-7435> \$78.00
<https://www.carpet-cleaning-equipment.net/rotovac-e-2500h-parts/> \$118.18
<https://www.kleen-ritecorp.com/p-44810-mytee-e519-heating-rod-1000-watt-115-volt.aspx> \$54.52
-->

Availability: This product was added to our catalog on Friday 29 May, 2009