


>



PART NO.	QTY	DESCRIPTION
02-01790	1	BLOWER ASSEMBLY MOTOR/BLADES/SHIELD/COVER/220VAC
02-01612	1	BLOWER ASSEMBLY MOTOR/BLADES/SHIELD/COVER/220VAC
02-01612	1	BLOWER ASSEMBLY MOTOR/BLADES/SHIELD/COVER/220VAC
02-01612	1	BLOWER ASSEMBLY MOTOR/BLADES/SHIELD/COVER/220VAC
02-01612	1	BLOWER ASSEMBLY MOTOR/BLADES/SHIELD/COVER/220VAC
02-01612	1	BLOWER ASSEMBLY MOTOR/BLADES/SHIELD/COVER/220VAC

Model Number: 108407

Legend Brand 108407 Drieaz Blower Motor Assembly for 7000, Syclone, 2800i, 3500i. Former part S559 02-01612 All Sales Final

Manufacturer: Legend Brand

Legend Brand 108407 Drieaz Blower Motor Assembly for 7000, Syclone LGR145XLi, 2800i and 3500i.

Wet location fan and motor assembly

For use in Phoenix 200 Max, R175, R200, R250, LGR145XLi, 7000xli, 2800i, and 3500i dehumidifiers

Former part numbers Include:

- S559
- 02-01790
- 02-01612
- 108407
- Uom
- 02-01612

All sales final. What does this mean?

2024-07-23 Legend brands stated if this item wobbles in any fashion it was caused by shipping and will not be replaced. This includes items that arrive with zero box damage and box dents. We have submitted past issues with the factory showing how we bubble wrap each item extensively and they refuse to supply the dealer or the end user with a replacement. No shipping claim can be filed with UPS / Fedex / US Post Office since the box will have zero damage along with item with zero damage. This means if you purchase this items and it wobbles or does not work, we will not purchase a replacement unit for you for free any longer. For years we took our \$4 profit we were paid for selling these and would purchase a replacement \$200+ item out of our own pocket if any issues with the item took place. We can no long afford to keep replacing these for free. Purchasing this part means you do so at your own risk.

<https://www.google.com/url?sa=t&source=web&rct=j&opi=89978449&url=https://www.cleanservinc.com/catalogsearch/result/%3Fq%3DLegend%2B&and%2B108407%2BDri-Eaz%2BBlower%2BMotor%2BAssembly%2B7000LGR%2BXLi&ved=2ahUKEwj31eiboeeNAXVo78kDHUcsHBgQFnoECB8QAQ&usg=AOvVaw2ewQKpppq8AdXutZ6nxQ11> \$270.10

[https://www.google.com/url?sa=t&source=web&rct=j&opi=89978449&url=https://partsfloodequipment.com/blower-assembly-part-number-s559-formerly-listed-as-02-01612/&ved=2ahUKEwj31eiboeeNAXVo78kDHUcsHBgQFnoECDgQAQ&usg=AOvVaw342\\_TLBwRAPPJg30ovqeMj](https://www.google.com/url?sa=t&source=web&rct=j&opi=89978449&url=https://partsfloodequipment.com/blower-assembly-part-number-s559-formerly-listed-as-02-01612/&ved=2ahUKEwj31eiboeeNAXVo78kDHUcsHBgQFnoECDgQAQ&usg=AOvVaw342_TLBwRAPPJg30ovqeMj) \$271.66

>

-->

---

*Availability: This product was added to our catalog on Tuesday 02 March, 2021*