

>



Model Number: 3430-0381

Hypro 3430-0381, Roller Repair Kit, contains 1005-0004, 2112-0003, 1720-0014

Manufacturer: Hypro Pumps

Hypro 3430-0381 Repair Kit

Repair Kit includes:

- 8 x Super Rollers (# 1005-0004)
- 2 x Viton Seals (# 2112-0003)
- 1 x O-Ring (# 1720-0014)

\*\*\* Special order from factory, expect 4 - 5 weeks for delivery

---

*Availability: This product was added to our catalog on Thursday 15 June, 2023*