

>



Model Number: TH-260

Turboforce TH260 Replacement Hard Boot Ring 12 Inches for TH40 Hybrid Wand VersaTile 67-054 [TH-260]

Manufacturer: Turbo Force

Repairs your Turboforce TH-40 Hybrid, US Products HFT-40, and VersaTile VT1200 wand hard boot ring lip

OD 12-7/16"

ID 11-3/16"

H 7/8"

OEM Association:

Sapphire Scientific 67-053

Repairs the Following Equipment:

VersaClean VersaTile VT1200 67-039 Tile and Grout Extractor Hard Surface Cleaning Machine

Turboforce: Turbo Hybrid Tile Cleaning Spinner Wand TH-40
And Us Products HFT-40

Rotovac

--> 20121222djc

Availability: This product was added to our catalog on Friday 17 June, 2011