

>



Model Number: 100900

Legend Brands 100900 Truckmount Heater Core Copper GT Blazer Peak - 63-268 - 8.631-844.0

ALL Orders FINAL

Manufacturer: Legend Brand

Legend Brands 100900 Copper Heater Core for Prochem GT Truckmounts
Part #100900 is a copper/aluminum truckmount heater core assembly used on select Prochem / Legend Brands GT model truckmount carpet cleaning machines. This heat exchanger helps transfer exhaust heat into the truckmount water system to produce hot cleaning solution.

Important: All orders for this replacement heater core are final. Please confirm your machine model and part number before ordering.

Fits / Commonly Used On

Machine / Model Reference
Notes

Prochem Apex GTX
GT model copper heater core

Prochem Peak GTX
GT model copper heater core

Legend GT
Verify serial number / parts manual

Blazer GT
Verify serial number / parts manual

Cross Reference / Associated Part Numbers

- Legend Brands 100900
- Sapphire Scientific 63-268
- 8.631-884.0
- 86318840
- APEXGTX

Construction

- Copper heater core / heat exchanger assembly

>

- Made with copper and aluminum components
- Designed for truckmount exhaust heat recovery systems
- Shown as #14 in some parts diagrams

Before You Order

Truckmount heater cores can vary by model year, serial number, and factory revision. Please compare your existing heater core, machine model, and OEM part number before ordering. Photos are for reference only; the order is fulfilled by the part number purchased.

Shipping Notice

This item may ship from Steambrite inventory or directly from a supplier. Availability and lead times can change. Special order parts may require additional processing time and are not returnable once ordered.

Warranty / Final Sale Notice

Replacement repair parts are sold under the manufacturer's warranty terms only. Labor, downtime, loss of use, installation errors, and consequential damages are not covered by Steam Brite, Inc.

Used to convert hot air into hot water to place back into water box

#14 in photo

See disclaimer bottom of webpage:

FINS ON THE HEAT EXCHANGER CAN AND WILL OR CAN BE SMASHED IN. WE HAVE NUMEROUS TIMES TO HAVE THE FACTORY RESOLVE THIS ISSUE AND LEGEND BRANDS STATES THIS IS HOW THEY ARRIVE TO THEM AND THIS IS A NON WARRANTY ISSUE. THE FACTORY ALSO DOES NOT DOUBLE BOX THESE WITH 2 INCHES OF CUSHION BETWEEN THE OUTER WALL OF THE BOX AND THE CONTENTS SO UPS AND FEDEX WILL ALWAYS DENY A SHIPPING CLAIM.

WHY ARE WE STATING THIS? THE ABOVE STATEMENTS ARE ALWAYS THE CASE. EVERY CUSTOMER COMPLAINS THE FACTORY SHIPS BENT HEAT EXCHANGERS. WE CANNOT GET THE FACTORY NOR THE SHIPPING COMPANY TO PAY FOR THIS ISSUE. IN THE PAST, WE HAVE RE-PURCHASED NEW HEAT EXCHANGERS OUT OF OUR \$10 COMMISSION FOR SELLING THESE BUT WE CAN NO LONGER OFFER THIS FREE SERVICE. WE ARE NOT GETTING PAID ENOUGH TO REPLACE A \$400 ORDER OUT OF OUR \$10 COMMISSION. WE NEVER BEEN SUCCESSFUL IN HAVING THE FACTORY REPLACE THESE FOR FREE OR HAVE THE SHIPPING COMPANY PAY FOR A REPLACEMENT EITHER. ALL SALES ARE FINAL. NO MORE SHIPPING CLAIMS WILL BE HONORED. IF YOU PURCHASE FROM THIS WEBPAGE, YOU ARE GOING TO SELF INSURE THIS PURCHASE. -->

<https://www.superiorcleaningsolutions.com/product-p/8.631-884.0.htm> \$343.00

<https://shop.monsterjanitorial.com/century-400-part-8-631-884-0-assy-heater-core-cooper-gt/> \$347.99

-->

.

Important Shipping & Condition Notice ‐ Please Read Before Ordering

This heater core ships factory direct to the customer. Due to the thin aluminum cooling fins and the manufacturer's current packaging methods, these units

>

commonly arrive with cosmetic shipping damage such as bent fins, dented edges, or minor deformation during transit.

In some cases, units may also develop leaks caused by shipping impact. Legend Brands has advised that bent fins and similar cosmetic imperfections are considered normal shipping-related handling conditions and are not treated by the manufacturer as a warranty issue.

Please note that these heater cores are not typically double-boxed or heavily cushioned by the manufacturer. Because of the packaging style used by the factory, UPS and FedEx frequently deny shipping damage claims on these items.

We are providing this notice in advance because this has been a repeated issue experienced by many customers over the years. Historically, Steambrite has attempted to assist customers with replacements at our own expense; however, due to the high replacement cost of these heater cores, we can no longer absorb these losses.

By purchasing from this webpage, the buyer acknowledges and accepts the risk of possible cosmetic shipping damage and agrees that all sales are final. Shipping damage claims, cosmetic fin damage claims, and transit-related condition claims cannot be guaranteed for reimbursement or replacement.

If perfect cosmetic condition is critical for your application, we recommend considering local pickup or discussing alternative shipping arrangements before placing the order.

Availability: This product was added to our catalog on Wednesday 11 December, 2013