

Equipment: Carpet Cleaning Machines > Vacuum Cleaners > HEPA Concrete Dust Slurry Hazmat Vacuums >



Model Number: 20170125

CRB Clean Systems 20170125, CRB Repair kit for TM4 TM5, Includes E20 E27 E29 E31 E32 E35 E40 E41 E74 E126 - E200

Manufacturer: CRB Cleaning Systems

BACK ORDER 30 DAYS

CRB Clean Systems Repair kit for TM4 and TM5 machines 20170125

Includes:

5 x gears (E31, E32, E35, E40, E41 = 1 of each) (E200 5 Gears Kit )

1 x E27 Handle Connector lower part G

1 x E29 Handle Connector lower part E

4 x E20 Flanges (Limited Stock)

2 x E126 360 Cable holders

2 x E74 Handle cones (30 DAY BACK ORDER, FINAL SHADE OR COLOR IS NOT GUARANTEED)

Pictures

CRB Clean Systems E200 CRB Repair kit for TM4 and TM5 machines  
Gear Pack Strong Gears Includes E31, E32, E35, E40, E41 x 1 of each In Stock

1 x E29 Handle connector lower part E with screw E95 -->

Availability: This product was added to our catalog on Tuesday 24 January, 2017