



Model Number: 8.601-469.0

Karcher Windsor SWITCH ROTARY CAM 4 POS [8.601-469.0] 86014690

Manufacturer: Karcher Pressure Washing

Karcher Windsor SWITCH, ROTARY CAM, 4 POS [8.601-469.0] 86014690

1 needed per machine

Factory installed in:

## Voyager 2

Voyager Duo

### Commodore Duo

BRC 50/70 W

Compare to current or past OEM associations

8.601-469.0

86014690

[https://www.shopetsonline.com/product-p/LAN-8.600-719.0.htm?gclid=EAlaIQobChMI7cSp5OWy4QIVwsDACH0\\_4Q7FEAYYASABegJYwPD\\_BwE](https://www.shopetsonline.com/product-p/LAN-8.600-719.0.htm?gclid=EAlaIQobChMI7cSp5OWy4QIVwsDACH0_4Q7FEAYYASABegJYwPD_BwE) \$162.59

-->

*Availability: This product was added to our catalog on Tuesday 02 April, 2019*