

>



Model Number: 32 URAI DSL

Dresser Roots 32 URAI DSL Vacuum blower pump T30378020 5 week back order

Manufacturer: Howden Roots Blowers

Dresser Roots 32 URAI DSL Vacuum blower pump

****NOTE: THE FACTORY IS NO LONGER GOING TO HONOR PRICES BASED ON THE DATE SOLD RATHER WILL ADJUST THE PRICE BASED ON THE DATE IT SHIPS. THIS MEANS IF YOU SEE A BLOWER WEBPAGE FOR \$2000 TODAY, BUT THE BLOWER SHIPS IN 12 WEEKS FROM NOW, YOU WILL HAVE TO AGREE TO THE NEW PRICE AND WILL HAVE TO PAY THE DIFFERENCE BEFORE THE ITEM SHIPS.**

QUESTION: If I purchase a cross over blower and it does not fit, will Steambrite or the factory waive the 25% restocking fee?

ANSWER: No. To purchase a similar performing blower is your decision as it states on every webpage, "All other warranties, express or implied, including but not limited to, the implied warranties of merchantability and fitness for a particular purpose, are hereby disclaimed"

THANKS FOR YOUR UNDERSTANDING.

DSL means Dual Splash crankcase, that both sides have an oil bath where the gears are located.

Single Shaft blower

Can be mounted in any position (just move the breather port to the top), can be spun in either direction.

NOTE: Default shaft orientation is LEFT HAND -- Unit can be mounted with top hand crank, bottom hand crank, left hand crank or right hand crank. Can be spun in either direction. Simply change the mounting feet and relocate the breather port to the top.

Compare Dresser Roots VS Tuthill VS Gardner Denver / Sutorbilt Blower - Crossover Charts

http://store.tomlinequipment.com/index.php?main_page=product_info&cPath=8_1_3&products_id=23&zenid=uemliff4sej7uo23eqvq0ak2

-->

"These blower and vacuum pumps are for sale and use in the carpet cleaning industry only as some OEM configuration have special coatings, or even mounting holes drilled in them. Example These blowers won't work for Easy Air Package equipment as it is not drilled and tapped to mount a fan. All other applications for use outside the carpet cleaning industry cannot be guaranteed."

Important Option

>

Oil level must be topped off on new blowers
Oil level must be changed after 50 hour break in period.
Oil level must be changed every 200 hours after break in period.
Gardner Denver 28G46 Brand Blower Oil Aeon PD-XD Full Synthetic Formula
Extra Heavy Duty for High Heat Applications 28G47-QT

Howden Terms

Availability: This product was added to our catalog on Thursday 21 December, 2023