Parts & Accessories > Valves > Valve Repair Kits > PMF R800SN Repair Kit for V800 Valve with New Stem and Nut 120077 23-135

PMF R800SN Repair Kit for V800 Valve with New Stem and Nut 120077 23-135



Model Number: R800SN

PMF R800SN Repair Kit for V800 Valve with New Stem and Nut 120077 23-135

Manufacturer: Production Metal Forming

PMF: R800SN Repair Kit for V800 Valve with New Stem and Nut

Compare to current or past OEM associations:
Esteam 538-115
Sapphire 23-135
Legend Brands 120077

Availability: This product was added to our catalog on Monday 04 February, 2013

Steambrite Supply