

>



Model Number: R800SN

PMF R800SN Repair Kit for V800 Valve with New Stem and Nut 120077 23-135

Manufacturer: Production Metal Forming

PMF: R800SN Repair Kit for V800 Valve with New Stem and Nut

Compare to current or past OEM associations:

Esteam 538-115

Sapphire 23-135

Legend Brands 120077

*Availability: This product was added to our catalog on Monday 04 February, 2013*